

34 L 150 G;

015034

US EPA RECORDS CENTER REGION 5



514700

J.E.
H.O.P.
St. Louis Park
Feb 28 B

REILLY TAR AND CEMENT COMPANY

TO: Mr. H. L. Finch, St. Louis Park

OFFICE: Indianapolis, Indiana

FROM: T. E. Reilly

DATE: Feb. 17, 1969

SUBJECT: EQUIPMENT - ST. LOUIS PARK - REPLACING OF INSULATION ON #13 STILL
WORK ORDER 228 B

cc:

P. White, St. Louis Park
F. J. Meach, Office
R. J. Kennedy, Lab.
S. C. Boyle, Office
T. J. Ryne, Office
P. C. Reilly, Office.

C. F. Lecker, Office
R. J. Boyle, Office
H. R. Zornet, Lab.
G. A. Reilly, Office
W. Roszel, Office

Work order 228 B was established to cover the replacement of a 4" thick blanket of calcium silicate insulation on the #13 still that was damaged. The replacement has been occasioned by damage to the insulation due to a leak in the storm agitator line that was improperly repaired. It was felt that during the leak when the still had been re-started there was a loss of about 600 gallons of tar.

The estimated cost of the replacement insulation is \$2,470.00, with an additional cost of \$450.00 for Reilly clean-up labor and supervision, or a total cost of \$2,857.00.

The work has been completed.

Please make all charges for the work to General Ledger Account 153-228 B

Very truly yours,

J. E. Kelly
T. E. Reilly

SG:mcb

200791